


CS14_Wilmcote House_United Kingdom


Author	Steven Stenlund	BRE
Date	March 2015	

1.1.3 Garden side jamb



COLOUR CODE

DESCRIPTION/CHALLENGES



The sole responsibility for the content of this publication lies with the authors. It does not necessarily reflect the opinion of the European Union. Neither the EACI nor the European Commission are responsible for any use that may be made of the information contained therein.

EuroPHit

CS14_Wilmcote House_United Kingdom

Author Steven Stenlund BRE

1.1.3 Garden side jamb – site photo

Date March 2015


BEFORE



AFTER



DESCRIPTION/CHALLENGES



The sole responsibility for the content of this publication lies with the authors. It does not necessarily reflect the opinion of the European Union. Neither the EACI nor the European Commission are responsible for any use that may be made of the information contained therein.



CS14_Wilmcote House_United Kingdom


Author Steven Stenlund BRE

1.1.3 Garden side jamb – Thermal model

Date March 2015

No pre-refurbishment thermal modelling undertaken

Isotherms
(Lines of constant temp) Warm Inside (20°C)





Cold Outside (0°C)

FINAL STEP

Ψ -value = 0.04 W/mK

Colour code



The sole responsibility for the content of this publication lies with the authors. It does not necessarily reflect the opinion of the European Union. Neither the EACI nor the European Commission are responsible for any use that may be made of the information contained therein.

EuroPHit