


# CS14\_Wilmcote House\_United Kingdom

Author Steven Stenlund  
BRE


## 1.1.2 Street side Sill

Date March 2015



COLOUR CODE

DESCRIPTION/CHALLENGES



The sole responsibility for the content of this publication lies with the authors. It does not necessarily reflect the opinion of the European Union. Neither the EACI nor the European Commission are responsible for any use that may be made of the information contained therein.

**EuroPHit**

CS14\_Wilmcote House\_United Kingdom

Author Steven Stenlund BRE

1.1.2 Street side Sill – site photo

Date March 2015


BEFORE



AFTER



DESCRIPTION/CHALLENGES



The sole responsibility for the content of this publication lies with the authors. It does not necessarily reflect the opinion of the European Union. Neither the EACI nor the European Commission are responsible for any use that may be made of the information contained therein.

**EuroPHit**


# CS14\_Wilmcote House\_United Kingdom

Author Steven Stenlund  
BRE  
Date March 2015


## 1.1.2 Street side Sill – Thermal model

No pre-refurbishment thermal modelling undertaken


FINAL STEP



Colour code



$\Psi$ -value = 0.07 W/mK



The sole responsibility for the content of this publication lies with the authors. It does not necessarily reflect the opinion of the European Union. Neither the EACI nor the European Commission are responsible for any use that may be made of the information contained therein.

**EuroPHit**